

SECRET

OUT57387

SECRET 171938Z

1965 DEC 17 19 51Z

25X1

1. CAMERA B 23 WAS USED IN MISSION 8062 FLOWN ON 15 DECEMBER 17 DEC 1965
1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD.

B. 9R SIDE: SMALL STATIC DISCHARGE TRACES (EDGE STATIC AND ROLLER CHATTER) ARE PRESENT INBOARD AND OUT BUT ARE MORE PROMINENT OUTBOARD. FRAMES 2 THRU 4 CONTAIN AN ARRAY OF MINUS DENSITY DOTS ROUGHLY PARALLEL TO AND APPROXIMATELY 2.5" FROM THE OUTBOARD EDGE OF THE FILM. A MANUFACTURING SPLICE IS PRESENT IN FRAME 193.

C. 9L SIDE: EDGE FOG AND STATIC OCCUR ALONG BOTH EDGES THROUGHOUT THE MISSION. ROLLER CHATTER IS PRESENT ALONG THE OUTBOARD EDGE AND 1.5" FROM THE INBOARD EDGE. INTERMITTENT MINUS DENSITY STREAKS, BEGINNING AT THE TITLED EDGE AND RUNNING DIAGONALLY ACROSS THE FILM, ARE PRESENT ON FRAMES 349 TO 351, 414 TO 419, 483 TO 488 AND 540 TO 546. THEY ARE CAUSED BY CREASES IN THE FILM. A MANUFACTURING SPLICE IS LOCATED THROUGH FRAME 1667.

D. THE LAST TITLED FRAME IS 1984.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

DISTRIBUTION		
Cy No.	Office	Action
1	File	
	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
2,4,5	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy
Sanitized

SECRET

Declassification Review by NGA/DoD

-2-

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADED OR OBSCURED 15 PERCENT OF THE MISSION.

S E C R E T

-END OF MESSAGE-

1

1